


Monitor "W" Series



For mills with turn table bearings at the bottom of the mast pipe

501-1 - Wheel Section
 501-B - Wheel Complete
 For WC mills Specify 5 or 6 section wheel

120 - Pump Pole Coupler
 T1 - Furling Lever

PARTS LIST

4-1-3

MONITOR WB 6 1/2' & WC 8' MILLS

PART NO.	DESCRIPTION	PART NO.	DESCRIPTION
1A	Lower ball race	63A	Vane stem angle
2	Tower casting, 4 post	64A	Vane truss angle
2X	Tower casting, 3 post	68	Wheel spoke
3A	Crank case w/mill pipe	69	Outer wheel rim
4	Shield w/sheaves	70	Inner wheel rim
5A	Upper ball race	71	Blade w/74&75
6	Long bushing - 50. shaft	72A	Vane sheet
6 1/2	Short bushing - 50 shaft	74	Large blade clip
7	Pitman guide	75	Small blade clip
8	Crank gear	76	Oil collar f/50
9	Pinion gear	78	Lower chain end
10	Hub w/shaft - 6 1/2' (4 sec.)	79A	Swivel bail
10V	Hub w/shaft - 8' (5 sec.)	80	Upper chain end
10-6	Hub w/shaft - 8' (6 sec.)	82	Governor spring
11	Upper vane hinge	83	Brake spring
12	Lower vane hinge	85A	Swivel chain w/73
13	Latch	86A	Mill pipe
14	Sheave f/4	95	Balls w/spacers
15	Brake	97	Key f/50 shaft
16	Swivel w/54 1/2, bolts	501-1	Wheel section w/rims
17	Pump pole casting	*501-B	Wheel complete
18	Inner wire swivel	K501-1	Wheel section f/6 sec.
19A	Outer wire swivel	*K501-B	Wheel complete f/6 sec.
21	Case cover	120	Pump pole coupler
22	Lower piston rod guide	T-1-0	Tower plate f/WB
43	Oil ring	T-1-1	Tower plate f/WC
43/44	Oil ring w/bracket	T10	Furl lever f/WB
46	Oil trough	T11	Furl lever f/WC
49	Cover gasket		
50	Wheel shaft		
51	Crank gear shaft		
52	Pitman guide pin		
53	Pitman		
54	Piston rod w/nut		
54 1/2	Plate f/16 swivel		
55	Vane hinge pin		
56	Brake rod w/nut		
58	Sheave pin w/cotter		
59	Sheave pin		
60	Latch pitman		